

Asset No.	WB/001
Location	Freshford Village Hall Playing Field
Inscription	None
OS Grid Reference	784601
Size	
Description	Timber clad waste Bin
Construction	Timber clad waste Bin
Condition	Good
Life expectancy	10 years
Recommended repairs	Repair And recoat in 2018.
Cost	



Asset No.	WB/002
Location	Freshford Village Hall/Freshford Lane
Inscription	None
OS Grid Reference	784600
Size	
Description	Timber clad waste Bin
Construction	Timber clad waste Bin
Condition	Good
Life expectancy	10 years
Recommended repairs	Repair And recoat in 2018.
Cost	



Asset No.	WB/003
Location	Church Hill/Hill
Inscription	None
OS Grid Reference	789601
Size	
Description	Timber clad waste Bin
Construction	Timber clad waste Bin
Condition	Good
Life expectancy	10 years
Recommended repairs	Repair And recoat in 2018.
Cost	





Asset No.	WB/004
Location	Tyning East
Inscription	None
OS Grid Reference	788600
Size	
Description	Timber clad waste Bin
Construction	Timber clad waste Bin
Condition	Good
Life expectancy	10 years
Recommended repairs	Repair And recoat in 2018.
Cost	



Asset No.	WB/005
Location	Tynning Centre
Inscription	None
OS Grid Reference	787599
Size	
Description	Timber clad waste Bin
Construction	Timber clad waste Bin
Condition	Good
Life expectancy	10 years
Recommended repairs	Repair And recoat in 2018.
Cost	



Asset No. WB/006  
Location Dog Bin Ashes Lane  
Inscription None  
OS Grid Reference 781599  
Size  
Description BANES metal box.



Construction  
Condition Good  
Life expectancy 10 years  
Recommended repairs None



Cost

Asset No. GB001

Location Top of Dark Lane

Inscription None

OS Grid Reference 787602

Size 1200 by 600

Description

Construction Timber clad grit bin

Condition Poor

Life expectancy 5 years

Recommended repairs Repair broken hinges and recoat in 2016

Cost



01 December 2015



25 January 2021

**Recommended repairs in 2021**

**End of life**

**Either repair in-situ or replace with modern yellow grit box.**

**Say £250 - £350 for repair or replacement.**