

Asset No.	FPC/NB 001 August 2015
Location	High Street Junction with School and Surgery.
Inscription	Freshford Parish Council
OS Grid Reference	788600
Size	1800 wide, 930 high
Description	Hardwood with three glazed doors. One with with barrel bolt, two with key mortice locks. Soft backing pinboard. No key available for central and right hand doors.
Construction	Fixed to Stone wall.
Condition	Backing board sound. Warped glazed doors. Poor and worn finish.
Life expectancy	10 years.
Recommended repairs	Obtain keys. Remove glazed doors or refurbish? Sand and recoat. Work completed in 2016
Cost	£285



31 August 2015



17 January 2021

2021 Recommendations

Reinspected Jan 2021 following repairs by Younghusband Trust to remedy rainwater spillage from damaged gutters above.
Recommend either repair and refurbishment insitu at say £350 or or relocate to Galleries side wall or Village Hall external entrance.

Asset No.	FPC/NB 002 August 2015
Location	Park Corner, Freshord, junction of Pipehouse Lane, Ashes Lane and Freshford Lane.
Inscription	Presented by Friends of Freshford in 1993.
OS Grid Reference	781598
Size	1150 wide, 790 high
Description	Hardwood with two glazed doors with barrel bolts, lead covered pediment, fibre board pinboard.
Construction	Fixed to Stone wall. 22 years old.
Condition	Decayed backing board. Warped glazed doors. Poor and worn finish.
Life expectancy	5-10 years.
Recommended repairs	Replace backing Board with new plywood and self healing pinboard Remove glazed doors or refurbish? Sand and recoat.
Cost	Repaired in April 2016. Cost £400



31 August 2015



Repaired Board in 2016



17 January 2021

2021 recommendations

Either repair and recoat at cost of say £400 or consider removal. Is this Notice Board required?

Asset No.	FPC/NB 003 1st September 2015
Location	Midford Lane. NB in Limpley Stoke Parish.
Inscription	Community Notices
OS Grid Reference	780606
Size	1200 wide, 820 high
Description	Hardwood with two glazed doors. No locks just timber turn piece.
Construction	Free standing and mounted on two hardwood posts
Condition	Backing board sound. Warped glazed doors. Poor and worn finish.
Life expectancy	10 years plus.
Recommended repairs	Remove glazed doors or refurbish? Sand and recoat.
Cost	Repaired in 2016. Cost £200.



1st September 2015



16th January 2021

2021 Recommendations

Repair and recoat this Community Board at cost of say £250
£250.00

Asset No.	FPC/NB 004 August 2015
Location	The Tyning Sharpstone opposite Hardings Cottage.
Inscription	Freshford Parish.
OS Grid Reference	783596
Size	1200 wide, 820 high
Description	Hardwood with two glazed doors both with mortice locks and no keys. Hardwood pediment
Construction	Fixed to Stone wall.
Condition	Decayed backing board. Warped glazed doors. Condition and finish sound and recoated recently.
Life expectancy	10 years plus
Recommended repairs	Replace backing Board with new plywood and self healing pinboard Remove glazed doors or refurbish? Keys with Stuart Campbell Maintained by Stuart Campbell
Cost	Unknown. Work completed by Stuart Campbell.



31 August 2015



15 January 2021

2021 Recommendations

Either repair and recoat at cost of say £350
Stuart Campbell is longer prepared to look after this Notice Board
Consider Removal. Is this Notice Board required?

Asset No.	FPC/NB 005 First recorded in August 2015
Location	High Street fixed to The Shambles.
Inscription	Mrs W G Bath, Freshford RBLWS (1955 - 1988) "sevice not self"
OS Grid Reference	789600
Size	970 wide, 970 high
Description	Hardwood with two doors. Right hand glazed with mortice lock and no key. Left hand open and no glazing.
Construction	Fixed to Stone wall of cottage - The Shambles.
Condition	Backing board poor damp and damaged. Warped glazed doors. Poor and worn finish.
Life expectancy	3 years.
Recommended repairs	Obtain keys. Replace missing glazing Remove glazed doors or refurbish? Repair hardwood sand and recoat. Replace in short term. Is this Notice Board required?
Cost	Board removed at no cost in 2020



31 August 2015

Removed in 2020
Inscription "Winnie Bath" sent to the Bath family
2021 Recommendations
None