

April 2020			
FPC Asset	Value	Totals	Comment
BENCHES			
Bench B001 Tyning	600		
Bench B002 Tyning	600		
Bench B003 Tyning	600		
Bench B004 Footpath east of FVMHall	500		
Bench B005 Outside Village Hall	600		
Bench B006 Midford Lane	600		
Bench B008 Station bench	1,000		
Bench B009 New Jenkins iron bench	3,000		New iron bench fixed around the Tyning Boar Oak in 2020
TOTAL BENCHES		4,500	
CEMETERY			
Cemetery Grounds			
Cemetery Boundaries	13,000		
Cemetery Headstones and monuments.			
Cemetery Gates	2,000		
Cemetery Shed	500		
TOTAL CEMETERY		15,500	
FRESHFORD Station Signs			
Freshford Station Signs	10,000	10,000	
HIGH STREET LION			
High Street Lion	10,000	10,000	
NOTICE BOARDS			
Notice Board 001 School/Surgery	1,500		
Notice Board 002 Park Corner	1,000		
Notice Board 003 Midford Lane	1,000		
Notice Board 004 Sharpstone	1,000		
TOTAL NOTICE BOARDS		4,500	
PARK CORNER PUMP			
Park Corner Pump	5,000	5,000	
THE POUND			
The Pound	0	0	
THE TYNING			
Tyning Field	33,765	33,765	
Tyning Boundary Walls and Fences.			
WAR MEMORIAL			
War Memorial	15,000	15,000	
FINGER POSTS			
Park Corner	2,000		
School/Surgery	2,000		
High St/Tyning	2,000		
Top Rosemary Lane	2,000		
Staples Hill	2,000		
Crowe Lane junction	2,000		
SAC The Inn/Bridge	2,000		
SAC Church Lane	2,000		

FPC Asset	Value	Totals	Comment
TOTAL FINGER POSTS		16,000	
INN RAILINGS			
Inn Tree protection	500		
Road railngs opposite the Inn	5,000		
TOTAL RAILINGS		5,500	
FRESHFORD PLAQUES			
Freshford Station	100		
Vaisey Plaque	100		
Mount Pleasant	100		
Cemetery Plaque "Bowden"	75		
TOTAL SIGNS/PLAQUES		375	
STREET LIGHTS			
Street Lights	115,000	115,000	See Street Lights tab. - 39 in total.
MILLENNIUM STONES			
MS3 Upper Pipehouse	250		
MS6 Midford Lane	250		
MS8 St Marys	250		
MS9 Hillside Farm Church Lane.	250		
MS10 Crowe Lane/Avenue Cottage	250		
MS12 Beyond Freshford Station.	250		
MS13 Footpath to Avoncliffe	250		
MS14 Staples Hill	250		
MS17 Dunkirk Cottage	250		
MS20 farthings Cottage Rosemary Lane	250		
TOTAL MILLENNIUM STONES		2,500	
OTHER ASSETS			
Village Projector	700		
Computer	870		
Strimmer	1,100		
Litter Bins	1,000		
Defibrillator	1,500		
TOTAL OTHERS		5,170	
Asset Value - Replacement Costs	245,810	242,810	

Light no.	Location	Unit Position	All or Part Night Burning	Column Type	Lantern Type	Condition	Comment
1	Nr Woodside House	P/E	Part	SSE Pole	Windsor	Good	
2	100 yards from Inn at Freshford	VE	Part	SSE Pole	Windsor	Good	Repair quote rec'd and instructed?
3	Opposite The Inn	VE	Part	Ornate	Windsor	Good	
4	On Jasmine Cottage	OB	All	Wall Bracket	Beta 76	Poor	Quote rec'd and instructed
5	The Hill Opposite Station Road	PA	Part	SSE Pole	DW Windsor	Good	Replaced March 2014
6	Opposite Manor/Station Road	PA	Part	SSE Pole	Windsor	Good	
6A	Station Road	PA	All		Gamma 6	Good	
7	On Laurel House	OB	Part	Wall Bracket	N/A	Poor	Refurbished 2017
7A	Station Approach	VE	Part	SSE Pole	SSE Pole	Good	
8	By Phone Box, High Street	PA	Part	Old Ornate Column	N/A	Poor	
9	Opposite Church Hill Cottage	PA	Part	Old Ornate Column	N/A	Poor	Replaced 2018
10	Opposite Home Farm House / Old Rectory	OB	Part	Wall Bracket	N/A	Poor	Replaced 2018
11	On The Old Grey House	OB	Part	Wall Bracket	Windsor	Good	
13	Opposite the Rockery	PA	Part	SSE Pole	Windsor	Good	
14	Opposite School	PA	Part	SSE Pole	Windsor	Good	
14A	Next to school gate		Part	SSE Pole	Windsor	Good	New Sept 2015 (Electricity supply comes from School)
15	Freshford Lane between School and Hall	VE	Part	SSE Pole	Windsor	Good	
18	Freshford Lane by garages	VE	Part	SSE Pole	Windsor	Good	
19	Freshford Lane, Junction of Park Corner	PA	Part	SSE Pole	Windsor	Good	
20	Pipehouse Lane	VE	Part	SSE Pole	Windsor	Good	Quote rec'd and instructed?
21	Pipehouse Lane	VE	Part	SSE Pole	Windsor	Good	
22	Junction A36, Pipehouse Lane	VE	Part	CV Galv	SGS 201	Good	
23	By House 1	VE	Part	SSE Pole	Windsor	Good	
24	Opposite Rose Cottage	VE	Part	SSE Pole	Windsor	Good	
25	Abbey Lane	VE	Part	SSE Pole	Windsor	Good	
26	Rosemary Lane junction with Abbey Lane	VE	Part	SSE Pole	Windsor	Good	
27	Rosemary Lane	VE	All night PEC	SSE Pole	Windsor	Good	
28	Rosemary cottage	OB	Part	Wall Bracket	Windsor	Good	Replaced March 2014
29	Glen Cottage	OB	Part	O.W	Old GEC	OK	
30	Sharpstone	PB	Part	SSE Pole	Old GEC	OK	
31	Sharpstone	PB	Part	Windsor	Windsor	Good	
32	Opposite Friars Gate Garage	PB	Part	SSE Pole	Windsor	Good	
33	Opposite Methodist Church	OB	Part	SSE Pole	Windsor	Good	
34	Outside House 6	PB	Part	SSE Pole	Windsor	Good	

Light no.	Location	Unit Position	All or Part Night Burning	Colume Type	Lantern Type	Condition	Comment
35	Out side House 2	PB	Part	SSE Pole	Windsor	Good	
36	War Memorial	PB	Part	SSE Pole	Windsor	Good	
37	Midway along the Tyning	VE	Part	URBIS	Windsor	Good	
38	Opposite Fairlawn	PA	Part	URBIS	Windsor	Good	
39	Outside the Shambles	OB	Part	Wall Bracket	Windsor	Good	